

A
 $S=2,2\text{ mA/V}$
 $\mu=66$
 $R_i=30\text{ k}$
 $P_a=\text{max } 1\text{ W}$

B
 $S=6\text{ mA/V}$
 $\mu=5,5$
 $R_i=920\ \Omega$
 $P_a=\text{max } 10\text{ W}$

